

**TABLE 10**  
**Apparent Free-Product Thickness Measurements**  
**August 1994 through May 1996**  
**Livingston Rail Yard, Livingston, Montana**  
**1996 Annual Groundwater Report**

Well	Aug-94	Nov-94	Feb-95	May-95	Aug-95	Nov-95	May-96	Avg.
LS-7	0.09				Well abandoned in 12/94			0.09
LB-4	0.48	0.81	0.12	0.45	0.65			0.50
L-87-2	ND	ND	ND	ND	ND	ND	ND	N/A
L-87-4	0.11		ND	ND	0.19	0.1		0.13
L-87-7	0.3	0.68	0.78	0.24	0.65	0.7	0.24	0.51
L-87-8	0.43	0.15	1.35	0.12	0.31	0.27	0.11	0.39
HRO-6	0.25	0.56	0.63	0.36	0.52		0.65	0.50
HRO-8		0.21			ND			0.21
HRO-9	0.02		0.06				0.03	0.04
HRO-10		ND	<0.01		<0.01		ND	N/A
HRO-11		0.11		0.23	ND			0.17
HRO-12	ND	ND	<0.01	ND	ND		ND	N/A
HRO-13	ND	ND	ND	ND	ND		ND	N/A
HRO-14		ND	ND	<0.01			ND	N/A
HRO-15	0.06	0.07	0.07	<0.01				0.07
HRO-16	ND	0.09	0.5	0.04				0.21
HRO-20	ND	<0.01	0.13	ND	0.06	0.16	0.03	0.10
HRO-21	ND	<0.01	<0.01	ND	ND	<0.01	ND	N/A
HRO-22	<0.01	<0.01	ND	<0.01	ND	0.01	ND	0.01
HRO-23	<0.01	<0.01	ND	ND	ND		ND	N/A
HRO-24	ND	0.08	0.14	0.01	0.14	0.24	ND	0.12
RW-1		<0.01	ND	0.01			ND	0.01
RW-2		<0.01	ND	<0.01			ND	N/A
RW-3		0.04	0.03	<0.01				0.04
RW-4		0.16	ND	0.16			0.04	0.24
RW-5		0.09	0.07	0.24				0.13
RW-6		1.07	0.14*	0.22*			0.13	0.60
RW-7	0.04	0.02	0.4	0.04	0.19	0.25	ND	0.16
RW-8	<0.01	0.01	0.02	0.03	0.15	0.17		0.08
RW-9	ND	ND	ND	ND	ND	0.01	ND	0.01
LG-11							ND	N/A
LG-12							ND	N/A
95-1							ND	N/A
LPZ-100		0.09	0.04					0.07

Notes:

ND - no product detected

<0.01 - Trace of product detected but less than resolution of product probe

\* - Approximately 35 gallons of product recovered from Well RW-6 during December 1994

